




Re: FW: Pine View Estates 
Aaron Setran to: David Albright
Cc: Rich Campbell

10/07/2008 04:05 PM

 Aaron Setran *Dave: The current permit does require notification to EPA upon the dis*

Dave:

The current permit does require notification to EPA upon the discovery of "surfacing effluent"; Part II.D.1.a.ii. I spoke w/ Pineview's contractor this afternoon and instructed her to provide a report (ASAP) to EPA which provides salient details concerning the leak at the leach field. I also told her that a NOV from EPA related to the issue is a possibility.

Aaron Carr Setran
U.S. EPA, Water Division
75 Hawthorne St.
San Francisco, CA 94105
(415) 972-3457
David Albright/R9/USEPA/US

David Albright/R9/USEPA/US

10/03/2008 02:13 PM

To Aaron Setran/R9/USEPA/US@EPA

cc

Subject

Re: FW: Pine View Estates

B5

Aaron Setran/R9/USEPA/US

Aaron Setran/R9/USEPA/US

10/03/2008 02:00 PM

To "Joe Maez" <jmaez@ndep.nv.gov>

cc David Albright/R9/USEPA/US@EPA

Subject

Re: FW: Pine View Estates

Joe:

I spoke w/ the folks at Pineview this morning and they told me that they are aware of the surfacing effluent problem at the each of their large leach field. They told me that one of the pressure lines had a leak, and that they are waiting for the replacement part which should arrive today or tomorrow. They'll repair the line as soon as they get the replacement part. likely over the weekend. According to Pineview, the leak in the pressure line has existed for about a week. Once the repair is done they said that they would notify me, and in turn, I let you know.

Given this information, and my previous inspections at the site, I don't believe that the vegetation in the catch basin at the bottom on the hill is being driven by effluent. As I mentioned on the telephone, surface water run-off from the streets and individual properties runs off into a storm drain collection system at the site, and some of this ends-up in the catch basin.

Aaron Carr Setran
U.S. EPA, Water Division
75 Hawthorne St.
San Francisco, CA 94105
(415) 972-3457

